




02-036B  
2 May, 2007

**STATUS TEMP CARD MODIFICATION FOR MOLY TEMP WARNINGS**

- I. **PURPOSE:**  
To guide you through modifying the status temp card to prevent intermittent moly temp warnings in the Teledyne API M101A, M200A, M200AU, and M201A Analyzers.
- II. **TOOLS:**  
Soldering iron  
Diagonal cutters  
Razor blade or “exacto knife”
- III. **PARTS:**  
KIT000125
- IV. **PROCEDURE:**
  - a. Follow the directions on the drawing on page two of this note.



Status Temp Card Modification for Moly Temp Warnings

02-036 Rev B

Page 2 of 2