



Service Note 08-017

Rev A

23 October, 2008

M700E Photometer Retrofit Information

I. PURPOSE:

This is an informative service note. The photometer option for the M700E cannot be installed in the field. If the M700E dynamic dilution calibrator was originally ordered without the photometer, and the photometer (Option 2A) has become desirable, the calibrator will need to be returned to the factory for installation.

II. TOOLS:

None

III. PARTS:

050000000 M700E (CE) CALIBRATOR ASSEMBLY

055210000 OPTION, PHOTOMETER, M700E (KB)



The electronics used in T-API analyzers are sensitive to Electrostatic Discharge (ESD). When working on any T-API device, please ensure that you are properly grounded prior to handling or touching any electronic circuitry in the analyzers! For more information on how to protect sensitive components from ESD during handling, please contact T-API Customer Service and ask for the ESD Service note number 03-022A.

IV. PROCEDURE:

No Procedure. Informative service note only.