

Service Note

A Teledyne Technologies Company

9480 Carroll Park Dr., San Diego, CA 92121-5201

Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190 E-mail: api-customerservice@teledyne.com http://www.teledyne-api.com

08-020 *Rev. A* November, 26th 2008

INFORMATION ON TELEDYNE-API HIGH LEVEL OZONE ANALYZER O-RING REPLACEMENT INTERVAL

I. PURPOSE:

To give information on the recent change in policy on the replacement of o-rings on the High level analyzers. Affected models:

M452

M454

M465H

M460H

M450H

II. TOOLS:

None.

III. PARTS:

None.

IV. PROCEDURE:

This service note is an information only type. This document informs you of a recent change to the recommended interval for replacement of the o-rings in the high level analyzers.

The o-rings should be replaced at least every 3 years. Please update your maintenance schedules and associated documents.

If the o-rings are not replaced, there may be potential that the o-rings will leak and allow sample gas to escape.

If you have any questions regarding this Service Note, please contact the Customer Service Department at api-customerservice@teledyne.com or at (858) 657-9800.