



TELEDYNE INSTRUMENTS

Advanced Pollution Instrumentation

A Teledyne Technologies Company
9480 Carroll Park Drive, San Diego, CA 92121-5201
Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190
E-mail: api-customerservice@teledyne.com <http://www.teledyne-api.com>

Service Note

94-005B
2 May, 2007

PULLEY DRIVE BELT PROBLEMS

We have had some problems with the drive pulley. The failure mode has been drive belts breaking.

We now have a new improved belt made using a different process that eliminates that problem. If you have any OR23 or OR24 white or yellow in color, we will exchange them with new belts. The new belts have the same Part Number but are black in color.

The belt Part Number is OR-23 for SO₂ and OR-24 for NO_x.

If you would like to exchange belts, please advise.