

# Service Note

Advanced Pollution Instrumentation

A Teledyne Technologies Company 9480 Carroll Park Drive, San Diego, CA 92121-5201

Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190 E-mail: api-customerservice@teledyne.com http://www.teledyne-api.com

**Rev xA** 07-025 NOTAL 13 December, 2002

## **New Moly Converters With Internal Quartz Wool Filters - Informative Note**

#### I. PURPOSE:

This is an informative service note. The moly converter that you have received with this service note are using a new internal quartz filter to help reduce any "white powder" from coming out of the moly converter. If you see any of this powder coming out of this moly converter we request that you contact customer service as soon as possible.

We plan on implementing these quartz wool filters in all of our moly converters, but we are sending out a few for testing before changing the design of the moly converter for production analyzers.

### II. TOOLS:

None

#### III. PARTS:

010150201 ASSY, MOLY CONV CARTRIDGE w/QUARTZ WOOL



The electronics used in T-API analyzers are sensitive to Electrostatic Discharge (ESD). When working on any T-API device, please ensure that you are properly grounded prior to handling or touching any electronic circuitry in the analyzers! For more information on how to protect sensitive components from ESD during handling, please contact T-API customer service and ask for the ESD Service note number 03-022A.

#### IV. PROCEDURE:

1. No Procedure. Informative service note only.

New Moly Converters With Internal Quartz Wool Filters - Informative Note

07-025 Rev \_\_\_xA\_\_\_

Page 1 of 1

CSF0001E 3/4/02