

9480 Carroll Park Dr., San Diego, CA 92121-5201  
 Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190  
 E-mail: [api-customerservice@teledyne.com](mailto:api-customerservice@teledyne.com) <http://www.teledyne-api.com>

**14-006 A**  
**Sept 03, 2014**

**VERSION OF 602BETAPLUSMANAGER.NET**

**I. PURPOSE:**

To inform our customers about 602 BetaPlus Manager Software compatibility with the Model 602 firmware version installed in their instrument.

**II. TOOLS:**

None

**III. PARTS:**

None.

This service note is for general information on using 602BetaPlus Manager Software. We recommend that all customers using 602BetaPlus Manager Software, use version **02.01.01** or newer to ensure compatibility with the firmware installed in your Model 602 and avoid potential parameter reset errors.

Contact the Teledyne API for more information.

How to figure out what version you are currently running:

Open 602Beta<sup>PLUS</sup> Manager.Net → Click on Teledyne Logo → About



Version of 602betaplusmanager.net  
 14-006 Rev A (DCN6962) 09/4/14

Page 1 of 1

PRINTED DOCUMENTS ARE UNCONTROLLED

CSF0001J (DCN6504)