



A Teledyne Technologies Company 9480 Carroll Park Drive, San Diego, CA 92121-2251 Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190 E-mail: <u>api-customerservice@teledyne.com</u> <u>www.teledyne-api.com</u>

> 02-021B 2 May, 2007

INFORMATION ON NEW TAPI PUMPS

I. <u>PURPOSE</u>:

To inform our customer of new updated pumps.

- II. <u>TOOLS</u>: None
- III. <u>PARTS</u>: None

IV. <u>PROCEDURE</u>:

To increase performance & to decrease the maintenance costs associated with the TAPI air pollution monitors we have made some changes to the pumps that we use in some of our products.

To help transition us into the new pumps we have begun putting stickers on the pumps that inform the user what the TAPI part number is of the pump & also the TAPI part number of the rebuild kit for the pump. If you find that there is not a sticker on it that tells you what part number is, & you have a questions, please note the Manufacturers part number & contact the TAPI sales department & they can provide you with a TAPI part number & price. The TAPI sales department can be reached at <u>API-sales@teledyne.com</u> or at the fax number at the fax number at the top of this informational service note.

As always, if you have any questions regarding the performance or troubleshooting of any of the TAPI instruments, please feel free to contact us, via any of the mediums listed above.

Information on New TAPI Pumps 02-021 Rev <u>B</u> Page 1 of 1