

Service Note

Advanced Pollution Instrumentation

A Teledyne Technologies Company 9480 Carroll Park Drive, San Diego, CA 92121-5201

Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190 E-mail: api-customerservice@teledyne.com http://www.teledyne-api.com

07-006A 27 March, 2007

REQUIRED OPTIONS FOR THE M701 WHEN USED WITH AN M300EU

I. PURPOSE:

This is an informational note only. Through testing of aged scrubbers it has been determined by TAPI that if you plan on using the M701 or M701H to generate zero air for the M300EU you must have the HC/CO scrubber option, OPT 2B. The CO only scrubber option does not have the capabilities over years of operation to sufficiently scrub out CO.

If your M701 does not have the HC/CO scrubber option installed in it and you plan on using it for the M300EU CO analyzer you will want to purchase KIT-40. This is a retrofit kit that will have all the necessary parts to install the HC/CO scrubber into your M701.

II. \underline{TOOLS} :

None

III. \underline{PARTS} :

KIT000040 RETROFIT, HC SCRUBBER, M701

IV. PROCEDURE:

1. Informational note only.