Service Note

Advanced Pollution Instrumentation

A Teledyne Technologies Company 9480 Carroll Park Drive, San Diego, CA 92121-5201

Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190 E-mail: api-customerservice@teledyne.com http://www.teledyne-api.com

07-011A 25 May, 2007

Population of Solid State Relays on the Relay Board

I. <u>PURPOSE</u>:

This note provides information of relay board population.

II. <u>TOOLS</u>:

N/A

III. PARTS:


N/A

IV. <u>REFERENCES</u>:

N/A

IV. **PROCEDURE**:

The different models of analyzers have different needs for heaters and other high current components. These components are each controlled by a relay, and the relay board can have up to 5 relays. Teledyne-API policy has changed so we are not installing a relay unless that component is installed for your individual instruments configuration. So if the relay board does not have all of the slots populated with relays – don't be alarmed.



Population of Solid State Relays on the Relay Board 07-011 Rev A Page 1 of 1