

Service Note

A Teledyne Technologies Company 9480 Carroll Park Drive, San Diego, CA 92121-5201 Phone (858) 657-9800 Fax: (858) 657-9818 Toll Free 1800 324-5190 E-mail: api-customerservice@teledyne.com http://www.teledyne-api.com

> 08-003 Rev A 17 March, 2008

## SO<sub>2</sub> UV LAMP MANUFACTURERS (informational note)

- I. <u>PURPOSE</u>: To inform customer of our different SO<sub>2</sub> UV lamp manufacturers. This service note is for informational purposes only
- II.  $\underline{\text{TOOLS}}:$ N/A
- III. <u>PARTS</u>: KIT000236



The electronics used in T-API analyzers are sensitive to Electrostatic Discharge (ESD). When working on any T-API device, please ensure that you are properly grounded prior to handling or touching any electronic circuitry in the analyzers! For more information on how to protect sensitive components from ESD during handling, please contact T-API customer service and ask for the ESD Service note number 03-022A.

## IV. <u>PROCEDURE</u>:

This note is to inform that we will be using two different manufacturers of UV Lamps in our  $SO_2$  products. One manufacturer's lamp wire colors will be grey/black and the other manufacturer's lamp wire colors will be white. Both of these lamps will be burned in prior to shipping out. Either UV lamp will work just fine in all of our sulfur products. For any additional information please contact our customer service department.

## SO<sub>2</sub> UV LAMP MANUFACTURERS (informational note) 08-003 Rev A Page 1 of 1

CSF0001E