



09-002 **Rev. A**
February 24, 2009

CONTACTING TELEDYNE API FOR ETHERNET PROBLEMS

I. PURPOSE:

To inform our customer that in the event that their analyzers should experience unexplained Ethernet problems, they should contact us here at the factory.

II. TOOLS:

None.

III. PARTS:

None.

This service note is an information only type. We recommend that if your analyzer experiences inconsistent and/or unexplained Ethernet errors; contact the Teledyne API factory for instructions. Customer service at Teledyne API can be contacted via telephone at (800) 324-5190 or (858) 657-9800 or via e-mail at api-customerservice@teledyne.com.